

Test Report

號碼(No.): ETR24C04126 日期(Date): 26-Dec-2024 頁數(Page): 1 of 4

中華紙漿股份有限公司觀音廠 (CHUNG HWA PULP CORPORATION - KUANYIN MILL) 桃園市觀音工業區國瑞路16號 (NO. 16, KUORUI ROAD, KUAN-YIN INDUSTRIAL DISTRICT, KUAN-YIN DISTRICT, TAOYUAN CITY 328453, TAIWAN)

以下測試樣品係由申請廠商所提供及確認 (The following sample(s) was/were submitted and identified by the applicant as):

送樣廠商(Sample Submitted By) : 中華紙漿股份有限公司觀音廠 (CHUNG HWA PULP CORPORATION - KUANYIN

MILL)

樣品名稱(Sample Name) : KRAFT TAPE(HM)

樣品型號(Style/Item No.) : 5 series

收件日(Sample Receiving Date) : 19-Dec-2024

測試期間(Testing Period) : 19-Dec-2024 to 26-Dec-2024

測試需求(Test Requested) : 依據客戶指定,測試鹵素-氟、氯、溴、碘。 (As specified by client, to test

Halogen-Fluorine, Chlorine, Bromine, Iodine in the submitted sample.)

測試結果(Test Results) : 請參閱下一頁 (Please refer to following pages).

Troy Chang / Department Makager Signed for and on behalf of Alwah SGS TAIWAN LTD. Chemical Laboratory - Taipei



PIN CODE: 64ACCB4F



Test Report

號碼(No.): ETR24C04126 日期(Date): 26-Dec-2024 頁數(Page): 2 of 4

中華紙漿股份有限公司觀音廠 (CHUNG HWA PULP CORPORATION - KUANYIN MILL) 桃園市觀音工業區國瑞路16號 (NO. 16, KUORUI ROAD, KUAN-YIN INDUSTRIAL DISTRICT, KUAN-YIN DISTRICT, TAOYUAN CITY 328453, TAIWAN)

測試部位敘述 (Test Part Description)

No.1 : 棕色膠帶 (BROWN TAPE)

測試結果 (Test Results)

測試項目 (Test Items)	測試方法 (Method)	單位 (Unit)	MDL	結果 (Result) No.1
氟 (F) (Fluorine (F)) (CAS No.: 14762-94-8)	參考BS EN 14582: 2016·以離子層析儀分析。 (With reference to BS EN 14582: 2016, analysis was performed by IC.)	mg/kg	50	n.d.
氯 (Cl) (Chlorine (Cl)) (CAS No.: 22537-15-1)	參考BS EN 14582: 2016 · 以離子層析儀分析。 (With reference to BS EN 14582: 2016, analysis was performed by IC.)	mg/kg	50	87.8
溴 (Br) (Bromine (Br)) (CAS No.: 10097-32-2)	參考BS EN 14582: 2016 · 以離子層析儀分析。 (With reference to BS EN 14582: 2016, analysis was performed by IC.)	mg/kg	50	n.d.
碘 (I) (lodine (I)) (CAS No.: 14362-44- 8)	參考BS EN 14582: 2016 · 以離子層析儀分析。 (With reference to BS EN 14582: 2016, analysis was performed by IC.)	mg/kg	50	n.d.

備註(Note):

- 1. mg/kg = ppm; 0.1wt% = 0.1% = 1000ppm
- 2. MDL = Method Detection Limit (方法偵測極限值)
- 3. n.d. = Not Detected (未檢出); 小於MDL / Less than MDL




Test Report

號碼(No.): ETR24C04126 日期(Date): 26-Dec-2024 頁數(Page): 3 of 4

中華紙漿股份有限公司觀音廠 (CHUNG HWA PULP CORPORATION - KUANYIN MILL) 桃園市觀音工業區國瑞路16號 (NO. 16, KUORUI ROAD, KUAN-YIN INDUSTRIAL DISTRICT, KUAN-YIN DISTRICT, TAOYUAN CITY 328453, TAIWAN)

鹵素分析流程圖 / Analytical flow chart - Halogen





Test Report

號碼(No.): ETR24C04126 日期(Date): 26-Dec-2024 頁數(Page): 4 of 4

中華紙漿股份有限公司觀音廠 (CHUNG HWA PULP CORPORATION - KUANYIN MILL) 桃園市觀音工業區國瑞路16號 (NO. 16, KUORUI ROAD, KUAN-YIN INDUSTRIAL DISTRICT, KUAN-YIN DISTRICT, TAOYUAN CITY 328453, TAIWAN)

* 照片中如有箭頭標示,則表示為實際檢測之樣品/部位. * (The tested sample / part is marked by an arrow if it's shown on the photo.)

ETR24C04126



** 報告結尾 (End of Report) **